

+

.125 100X **Z** | **K** 20X .625
 .250 50X **O** | **E** 10X 125
 .1875 62.5X **V** | **S** 31.25X .375

1.000 **D** | 10X
 .1875 **N** | 50X
 .4375 **J** | 20X

.125 **U** | 62.5X
 .250 **R** | 31.25X

.0625 **W** | 100X
 .125 **M** | 50X
 .625 **C** | 10X
 .1875 **D** | 31.25X
 .5781

.250 **H** | 20X

.0625 **T** | 62.5X
 .5790
 .1875 **G** | 20X
 .0625 **I** | 50X
 .5790

B | 10X
 .250
 .5790
P | 31.25X

F | 20X
 .0625
A | 10X
 .0625
P | 31.25X
B | 10X
 .250
L | 50X
 .0625
G | 20X
 .1875
T | 62.5X
 .0625

MAGNIFICATION CHECK SCALE

SET TO INSIDE EDGES OF LINES

.250 **H** | 20X

.1875 **Q** | 31.25X
 .625 **C** | 10X
 .125 **U** | 62.5X
 .250 **R** | 31.25X

.4375 **J** | 20X
 .1875 **N** | 50X

1.000 **D** | 10X

.1875 62.5X **V** | **S** 31.25X .375
 .250 50X **O** | **E** 10X 125
 .125 100X **Z** | **K** 20X .625

+